TEAC

TECHNICAL INFORMATION

No. **0701**

DATE 16th February 2007

CD-RW402(V3)/CD-RW2000(V3), Substitution of the Drive

This information relates to previous Tech-Info No. 0505R, 0506R, 0510 and 0511R.

The Drive (CD-W58DA) introduced in both info has been replaced with a RoHS conformity Drive (CD-W58DB) on the V3 products with the following S/Nos (month started production):

CD-RW402V3: S/N 0350001 and after (Nov/2005)
CD-RW2000V3: S/N 0500001 and after (Mar/2006)
Exception: T/C - S/N 0470076 to 047125 (Nov/2005)
All - S/N 0490116 to 049215 (Feb/2006)

Parts required

Item	Qty	P/No.	Description
New bare drive	1	V00141900A	CD-W58DB-T00 G
Drive update on CD-R			"W58db1td.abf" written
Drive update on Windows			"W58db1td.exe"

Visit the **ROM Data Library** on the SVHP to download the both firmware data and follow the update procedure on the previous Tech Info to read the following change:

"T58V1tf.abf" of CD-W58DA Drive => "W58db1td.abf" for CD-W58DB Drive.
"CDW58da1tf.exe" of CD-W58DA Drive => "W58db1td.exe" of CD-W58DB Drive.

Notice:

Do not attempt to write the former CD-W58DA firmware, "T58V1tf.abf" or "CDW58da1tf.exe" onto new CD-W58DB Drive otherwise new Drive becomes totally no response since type of Flash Rom fitted is quite different by the RoHS requirement. These firmware have no capability to identify type of Drive on which targeted to update therefore.