TEAC

TECHNICAL INFORMATION

No. **0702**

CD-RW700/RW-800, Substitution of the CD-RW Drive

DATE 16th February 2007

This information relates to previous Tech-Info No.0515.

The CD-W58DA Drive introduced in the Tech-Info has been no longer available and the CD-W58DB fitted in the new CD-RW2000V3 RoHS is used for substitution.

The CD-W58DB Drive programmed V1.TD firmware is provided for this purpose since TASCAM CD-RW700 and TEAC Hi-Fi RW-800 are unable to fit a Front MPU for the CD upgrade capability,

Parts required

Item	Qty	P/No.	Description
Old drive	1	V00140010A	DRIVE ASSY, CDW58DA RW700/800
New drive	1	V00162400A	DRIVE, CDW58DB RW700/800

Or provide the bare Drive of the CD-W58DB in case the circumstances of PC programming is available.

Item	Qty	P/No.	Description
New bare drive	1	V00141900A	CD-W58DB-T00
Drive update on Windows			"W58db1td.exe"

Visit the **ROM Data Library** in the TASCAM Service HP website to download firmware data image of "W58db1td.exe" into PC.

1. While PC is powered off, connect the CD-W58DB to PC and reboot.
   No need to consider Primary/Secondary and Master/Slave.
2. Double-click on "W58DB1TD.EXE" to run.
3. Follow the messages that will appear.

Follow the entire steps in the previous Tech-Info describes.