TASCAM
TEAC Professional Division

CD-RW2000V3

SERVICE MANUAL

SUPPLEMENT

追補版

The circuit diagrams here are applicable for CD-RW2000 S/No. 0390001 and higher.
Use this with the original CD-RW2000 Service Manual, Effective: June, 2000.

ここに記載されている回路図は、シリアル No. 0390001 以降の CD-RW2000 に適用されます。
CD-RW2000 のオリジナルサービスマニュアル、Effective: June, 2002 と共に使用してください。

Changes（変更内容）

1..To adopt a new CD-RW DRIVE, related components have been changed with renewal of Converter MPU and Front MPU accordingly.
DRAM on Converter PCB Assy has been changed due to its availability.
CD-RW DRIVEを変更するとともに、関連部品を変更しました。
DRAM入手難の為にPCBA,CONVERTER RW2 U709を変更しました。

2. To cope with above, the major difference of parts are as follows:
上記による主要な差異部品は以下の通りです。

1- 5	V00089500A	DRIVE ASSY,CD-W54E-A90	→	V00140000A	CD-W58DA-T00	
1- 7	3M0089930B	PANEL,TRAY 700	→	M02038200A	PANEL,TRAY RW2000 (ASS)	
1- 9	3M0088400A	BRACKET MECH SIDE(L)	→	M02038600A	BRACKET MECH (L) RW2000	
1-10	3M0088500C	BRACKET MECH SIDE(R)	→	M02038700A	BRACKET MECH (R) RW2000	
1-43	3M0088830A	ESCUTCHEON F,N66	→	M02038400A	ESCUTCHEON,FRONT, RW2000	
1- 3	*V00140600A	PCB ASSY,CONVERTER	→	3E9524720B	PCB ASSY,CONVERTER 2000V3	
	S00386800A	HD64F7044-CONVT3	→	3S0048510B	UCOM Assy,HD64F7044 402V3	U707 MPU
	S0036813	IC,MSM5118165D	→	S0060813	IC,T2316162A-50SIC	U709 DRAM
1-46	3E9527600A	PCB ASSY GATHER,FRONT	→	3E9527600A	PCB ASSY GATHER,FRONT	(No change)
	3S0035000A	IC,CXP82040-ROQFR	→	S00598300A	IC,CXP82040-160Q Front3 G	IC, U500

* This is newly registered P/N since CD-RW2000V3 is produced with an identical P/N.
Ensure the P/N by confirming the S/No. of the unit being repaired upon ordering it.
* CD-RW-2000V3は旧機と同一品番で生産されているため、新規に登録した品番です。
修理機の機番を確認のうえ、正しい品番で発注してください。

Effective: August, 2005