TEAC

TECHNICAL INFORMATION

CD-RW2000V3, Service Manual Supplement Correction

No. **0705**
DATE 20th March 2007

Correction is required on the service manual as shown below.

CD-RW2000V3, page 1 at right column of the parts list

Ref. No.	✕	○
1- 3	3E9527600A PCB ASSY, CONVERTER 2000V3	3E9524720B PCB ASSY, CONVERTER 2000V3
	3S0048510A UCOM Assy, HD64F7044 402V3IC U707 MPU	3S0048510B UCOM ASSY HD64F7044 402V3 U707 MPU

The service manual on the SVHP have been corrected on 14th/March/2007.