Important Firmware Installation Notes

For the MPK25 and MPK49:

- Install the v1.x firmware if

    A. The following highlighted serial number digits are 1103 or lower: (21)K3**1104**023100948

    or…

    B. If he unit's original v1 Main PCB has not been replaced with a v2 Main PCB through repair.

- Install the v2.x firmware if

    A. The following highlighted serial number digits are 1104 or higher: (21)K3**1104**023100948

Note: v1.x firmware cannot operate on units with v2 Main PCB installed. Also, v2.x firmware cannot operate on units with v1 Main PCB installed. v2 Main PCB was issued to allow for future production, replacing a component that was end of live. v2 Main PCB does not add any features or improvements.

The above does not apply to the MPK61 and MPK88.